

LIST OF ALL VALIDATED RADIOS TILL JUNE 2022

Astrid Support = Not supported - equipment was validated and can still be in use on the network but **Astrid will give no support** in case of eventual working issues
 Astrid Support = Supported - equipment was validated and can be used on the network. **Astrid will give support** in case of eventual working issues

Manufacturer	Model	RadioType	Software Version	Certificate Nr	Validation date	Supplier	Astrid Support
AIRBUS	DABAT	RC-53	V8.33-6	2020-01	13/01/2020	TranzCom	Supported
AIRBUS	DABAT	RC-53	V8.58-0	2021-02	15/01/2021	TranzCom	Supported
AIRBUS	TH1N	RC-36	V7.08-9	2014-08	09/10/2014	TranzCom	Not Supported
AIRBUS	TH1N	RC-36	V7.61-3-006(E2EE)	2015-09	18/11/2015	TranzCom	Not Supported
AIRBUS	TH1N	RC-36	V7.61-H	2016-03	21/03/2016	TranzCom	Not Supported
AIRBUS	TH1N	RC-36	V7.71-8	2017-08	20/04/2017	TranzCom	Supported
AIRBUS	TH1N	RC-36	V 8.55-5	2021-09	08/03/2021	TranzCom	Supported
AIRBUS	TH1N	RC-47	V7.71-8	2017-04	20/04/2017	TranzCom	Supported
AIRBUS	TH1N	RC-47	V 8.55-5	2021-10	08/03/2021	TranzCom	Supported
AIRBUS	TH9	RC-46	V7.62-2	2016-01	07/01/2016	TranzCom	Not Supported
AIRBUS	TH9	RC-46	V7.71-9	2016-09	30/08/2016	TranzCom	Not Supported
AIRBUS	TH9	RC-46	V7.71L	2017-01	05/01/2017	TranzCom	Not Supported
AIRBUS	TH9	RC-46	V7.84-4	2017-09	10/07/2017	TranzCom	Not Supported
AIRBUS	TH9	RC-46	V7.85-1	2018-07	30/01/2018	TranzCom	Supported
AIRBUS	TH9	RC-46	V 8.55-5	2021-03	15/01/2021	TranzCom	Supported
AIRBUS	THR9EX	RC-27	V7.08-9	2014-12	04/12/2003	TranzCom	Not Supported
AIRBUS	THR880i	RC-2	V7.08-9	2014-09	17/05/2010	TranzCom	Not Supported
AIRBUS	THR880i	RC-2	V7.61-H	2016-12	30/10/2016	TranzCom	Not Supported
AIRBUS	THR880i	RC-2	V7.93-1	2018-05	30/01/2018	TranzCom	Not Supported
AIRBUS	THR880i	RC-2	V8.30-9	2019-19	02/08/2019	TranzCom	Supported
AIRBUS	THR880i	RC-2	V8.55-5	2021-05	18/02/2021	TranzCom	Supported
AIRBUS	THR880i+	RC-10	V8.14-8	2019-13	06/06/2019	TranzCom	Supported
AIRBUS	THR880iEX	RC-12	V7.61-H	2019-12	06/06/2019	TranzCom	Supported
AIRBUS	THR880iWB	RC-10	V7.08-9	2015-07	25/06/2015	TranzCom	Not Supported
AIRBUS	THR880iWB	RC-10	V7.61-3	2015-10	24/11/2015	TranzCom	Not Supported
AIRBUS	THR880iWB	RC-10	V7.61-H	2017-06	10/07/2017	TranzCom	Not Supported
AIRBUS	THR880iWB	RC-10	V7.93-1	2018-06	30/01/2018	TranzCom	Supported
AIRBUS	THR880iWB	RC-10	V8.55-5	2021-06	18/02/2021	TranzCom	Supported
AIRBUS	THR9+	RC-32	V7.08-9	2014-10	30/08/2016	TranzCom	Not Supported
AIRBUS	THR9+	RC-32	V7.71-4	2018-18	10/07/2017	TranzCom	Supported
AIRBUS	THR9+	RC-32	V8.30-9	2019-20	30/01/2018	TranzCom	Supported
AIRBUS	THR9EX	RC-49	V7.71-9	2016-10	13/10/2014	TranzCom	Not Supported
AIRBUS	THR9EX	RC-49	V7.84-5	2017-07	18/04/2018	TranzCom	Not Supported
AIRBUS	THR9EX	RC-49	V7.85-1	2018-08	02/08/2019	TranzCom	Supported
AIRBUS	THR9EX	RC-49	V 8.55-5	2021-08	27/06/2021	TranzCom	Supported
AIRBUS	THR9i	RC-30	V7.08-9	2014-11	14/10/2014	TranzCom	Not Supported
AIRBUS	THR9i	RC-30	V7.71-3	2016-11	30/08/2016	TranzCom	Not Supported
AIRBUS	THR9i	RC-30	V8.30-9	2019-21	02/08/2019	TranzCom	Supported
AIRBUS	THR9i	RC-30	V8.55-6	2021-07	01/03/2021	TranzCom	Supported
AIRBUS	TMR880i	RC-9	V7.85-1	2018-09	30/01/2018	TranzCom	Not Supported
AIRBUS	TMR880i	RC-9	V8.30-9	2019-22	02/08/2019	TranzCom	Not Supported
AIRBUS	TMR880i	RC-9	V8.55-5	2021-11	15/03/2021	TranzCom	Supported
AIRBUS	TMR880i	RC-9	V8.73-6	2022-06	26/04/2022	TranzCom/Axiens	Supported
CASSIDIAN	TDR880i	RC-14	V1.42-0	2013-01	13/01/2013	TranzCom	Not Supported
CASSIDIAN	TH1N	RC-36	V6.70-9	2013-15	05/05/2013	TranzCom	Not Supported
CASSIDIAN	THR880i	RC-2	V6.59-8	2011-08	12/03/2013	TranzCom	Not Supported
CASSIDIAN	THR880i	RC-2	V6.69-7	2013-06	12/10/2014	TranzCom	Not Supported
CASSIDIAN	THR880iEX	RC-12	V6.59-8	2011-09	19/07/2011	TranzCom	Not Supported
CASSIDIAN	THR880iWB	RC-10	V6.69-7	2013-07	12/03/2013	TranzCom	Not Supported
CASSIDIAN	THR9+	RC-32	V6.62-A	2012-01	14/04/2013	TranzCom	Not Supported
CASSIDIAN	THR9+	RC-32	V6.69-7	2013-12	14/10/2014	TranzCom	Not Supported
CASSIDIAN	THR9EX	RC-27	V6.59-8	2011-05	01/03/2021	TranzCom	Not Supported
CASSIDIAN	THR9EX	RC-27	V6.60-8	2012-03	29/02/2012	TranzCom	Not Supported
CASSIDIAN	THR9EX	RC-27	V6.69-7	2013-13	14/04/2013	TranzCom	Not Supported
CASSIDIAN	THR9i	RC-30	V6.59-8	2011-04	28/04/2011	TranzCom	Not Supported
CASSIDIAN	THR9i	RC-30	V6.60-8	2012-02	27/06/2012	TranzCom	Not Supported
CASSIDIAN	THR9i	RC-30	V6.69-7	2013-11	14/04/2013	TranzCom	Not Supported
CLEARSTONE	CM5000	N/A	MR01.012.016	2009-05	29/01/2009	Securitas Technology NV	Not Supported
CLEARSTONE	CM5000	N/A	MR01.012.038.A01	2010-13	09/08/2010	Securitas Technology NV	Not Supported
CLEARSTONE	CM5000	N/A	MR01.312.046	2011-07	14/07/2011	Securitas Technology NV	Not Supported
CLEARSTONE	CM5000	N/A	MR01.312.048-00	2014-01	12/01/2014	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.36G4C-7	2003-01	21/03/2003	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.36G4D	2003-13	18/09/2003	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.36G4E	2004-08	02/06/2004	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.37A	2005-31	07/11/2005	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.38A	2008-02	23/01/2008	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.38A-002	2008-16	26/11/2008	Securitas Technology NV	Not Supported
CLEARSTONE	CM9000	N/A	V0.41	2011-07	27/06/2011	Securitas Technology NV	Not Supported
EADS	TDR880i	RC-14	V1.38	2009-01	15/01/2009	TranzCom	Not Supported
EADS	TGR990/CM5000	M31PCN6TZ5ANSP02	ER01.012.029	2010-08	20/06/2010	TranzCom	Not Supported
EADS	THR880	THR-4	V7.77-1	2008-09	09/12/2004	TranzCom	Not Supported
EADS	THR880i	RC-2	V4.22-0	2006-14	28/09/2006	TranzCom	Not Supported
EADS	THR880i	RC-2	V4.82-3(E2EE)	2006-27	19/02/2007	TranzCom	Not Supported
EADS	THR880i	RC-2	V4.82-A	2007-03	05/12/2007	TranzCom	Not Supported
EADS	THR880i	RC-2	V5.24-0	2007-22	24/06/2008	TranzCom	Not Supported
EADS	THR880i	RC-2	V5.82-2	2008-08	03/06/2010	TranzCom	Not Supported
EADS	THR880i	RC-2	V6.53-5	2010-05	19/07/2011	TranzCom	Not Supported
EADS	THR880iEX	RC-12	V5.82-2	2008-12	09/07/2008	TranzCom	Not Supported
EADS	THR880iEX	RC-12	V5.82-6	2009-06	10/03/2009	TranzCom	Not Supported
EADS	THR880iEX	RC-12	V6.53-7	2010-14	16/09/2010	TranzCom	Not Supported
EADS	THR880iLIGHT	RC-7	V4.24-8	2006-28	03/10/2006	TranzCom	Not Supported
EADS	THR880iLIGHT	RC-7	V4.24-8	2006-28	03/10/2006	TranzCom	Not Supported
EADS	THR880iWB	RC-10	V5.82-2	2008-07	16/06/2008	TranzCom	Not Supported
EADS	THR9	RC-20	V6.53-4	2010-03	21/06/2011	TranzCom	Not Supported
EADS	TMR880	TMR-1	V6.15-4	2004-03	26/01/2004	TranzCom	Not Supported
EADS	TMR880	TMR-1	V7.34-0	2004-20	09/07/2004	TranzCom	Not Supported

LIST OF ALL VALIDATED RADIOS TILL JUNE 2022

Astrid Support = Not supported - equipment was validated and can still be in use on the network but **Astrid will give no support** in case of eventual working issues
 Astrid Support = Supported - equipment was validated and can be used on the network. **Astrid will give support** in case of eventual working issues

Manufacturer	Model	RadioType	Software Version	Certificate Nr	Validation date	Supplier	Astrid Support
EADS	TMR880	TMR-1	V7.60-0	2005-19	03/06/2005	TranzCom	Not Supported
EADS	TMR880	TMR-1	V7.67-0	2005-22	27/09/2005	TranzCom	Not Supported
EADS	TMR880	TMR-1	V7.72-0	2006-21	23/06/2006	TranzCom	Not Supported
EADS	TMR880	TMR-1	V7.77-0	2008-10	29/06/2008	TranzCom	Not Supported
EADS	TMR880	TMR-1	V7.79-1	2010-04	03/06/2010	TranzCom	Not Supported
EADS	TMR880i	RC-9	V4.88-2	2006-34	23/11/2006	TranzCom	Not Supported
EADS	TMR880i	RC-9	V5.18-4	2007-08	19/03/2007	TranzCom	Not Supported
EADS	TMR880i	RC-9	V5.82-2	2008-13	13/07/2008	TranzCom	Not Supported
EADS	TMR880i	RC-9	V6.53-4	2010-06	03/06/2010	TranzCom	Not Supported
EADS	TMR880i	RC-9	V6.59-8	2011-10	19/07/2011	TranzCom	Not Supported
EADS	TMR880i	RC-9	V 6.69-7	2013-14	28/04/2013	TranzCom	Not Supported
EADS	TMR880i	RC-9	V7.71-C	2016-13	30/10/2016	TranzCom	Not Supported
EADS	TMR880i	RC-9	V7.84-3	2017-05	10/07/2017	TranzCom	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5154 (MRS.1.2)	2004-24	16/12/2004	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5158 (MRS.1.3)	2005-03	14/02/2005	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5433	2005-23	29/09/2005	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5544	2006-29	03/10/2006	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5620 (MRS.5)	2007-09	26/03/2007	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.5815 (MRS.6)	2007-23	13/12/2007	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.6213 (MRS.8)	2009-02	15/01/2009	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.7184 (MRS.11.1)	2010-07	07/06/2010	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.7869 (MRS.13)	2011-11	03/10/2011	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.8195 (MRS.14.3)	2013-04	27/01/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTH800	PT911FR	R07.020.8462 (MRS.14.9)	2013-21	16/12/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.8532 (MR10.6.9)	2013-19	18/11/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.8932 (MR15)	2016-07	14/04/2016	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.9063 (MR16.1)	2018-04	26/01/2018	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.9289 (MR17.3)	2019-04	16/01/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.9335 (MR18A)	2019-16	26/07/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTM5000	MT953C	R27.020.9426 (19.2)	2020-12	18/05/2020	Securitas Technology NV	Supported
MOTOROLA	MTM5000	MT953C	R27.020.9689 (MR2021.3)	2022-07	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	MTM5400	MT953C	R27.020.8276	2012-07	27/11/2012	Securitas Technology NV	Not Supported
MOTOROLA	MTM800E	MT912M	R17.020.6213 (MRS.8)	2009-04	20/01/2009	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PT9120F / PT9120FE / PT9120HE	R35.020.7644	2013-05	10/02/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PT9120F / PT9120FE / PT9120HE	R35.020.7691	2014-02	30/01/2014	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PT9120F / PT9120FE / PT9120HE	R35.020.8932 (MR15)	2016-06	14/04/2016	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PTB952HE and PTB952FE	R35.020.9174 (MR16.5)	2018-01	26/01/2018	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PTB952HE and PTB952FE	R35.020.9289 (MR17.3)	2019-01	16/01/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTP3000	PT9120HE	R35.020.9335 (MR18A)	2019-14	26/07/2019	Securitas Technology NV	Supported
MOTOROLA	MTP3000	PTB952HE	R35.020.9426 (MR19)	2020-07	18/05/2020	Securitas Technology NV	Supported
MOTOROLA	MTP6000	PT952A / PT952ACE	R33.020.7691	2014-07	05/08/2014	Securitas Technology NV	Not Supported
MOTOROLA	MTP6000	PT952A / PT952ACE	R33.020.8932 (MR15)	2016-04	21/03/2016	Securitas Technology NV	Not Supported
MOTOROLA	MTP6000	PT952AC/ PTAR952AC/ PT952ACE	R33.020.9174 (MR16.5)	2018-02	26/01/2018	Securitas Technology NV	Not Supported
MOTOROLA	MTP6000	PT952AC/ PTAR952AC/ PT952ACE	R33.020.9289 (MR17.3)	2019-02	16/01/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTP6550	PT952AC	R33.020.9334 (MR18)	2019-23	06/09/2019	Securitas Technology NV	Supported
MOTOROLA	MTP6650	PTAR952AC	R33.020.9335 (MR18A)	2019-24	06/09/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTP6650	PTAR952AC	R33.020.9426 (MR19)	2020-08	18/05/2020	Securitas Technology NV	Supported
MOTOROLA	MTP6650	PTAR952AC	R33.020.9426 (MR19)	2020-08	18/05/2020	Securitas Technology NV	Supported
MOTOROLA	MTP6750	PT952ACE	R33.020.9689 (MR2021.3)	2022-10	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	MTP8000EX	PT951NPK0158X	R36.020.8932 (MR15)	2016-05	11/04/2016	Securitas Technology NV	Not Supported
MOTOROLA	MTP8000EX	PT951NPEEX	R36.020.9063 (MR16.1)	2018-03	26/01/2018	Securitas Technology NV	Not Supported
MOTOROLA	MTP8000EX	PT951NPEEX	R36.020.9289 (MR17.3)	2019-03	16/01/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTP8000EX	PT951NPK0158X	R36.020.9335 (MR18.A)	2019-15	26/07/2019	Securitas Technology NV	Not Supported
MOTOROLA	MTP8000EX	PT951NPEEX	R36.020.9426 (MR19)	2020-09	18/05/2020	Securitas Technology NV	Supported
MOTOROLA	MTP8000EX	PT951NPEEX	R36.020.9689 (MR2021.3)	2022-11	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	MTP830S	PT912BF5	R13.020.8195 (MRS.14.3)	2012-06	27/11/2012	Securitas Technology NV	Not Supported
MOTOROLA	MTP830S	PT912BF5	R13.020.8462 (MRS.14.9)	2013-23	16/12/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT911B	R13.120.5551(E2EE)	2006-31	07/02/2007	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT911B	R13.020.5620 (MRS.5)	2007-02	13/12/2007	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT911B	R13.020.5815 (MRS.6)	2007-24	19/01/2009	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT911B	R13.020.6213 (MRS.8)	2009-03	26/04/2010	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT912B	R13.020.7184 (MRS.11.1)	2010-02	03/10/2011	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT912B5	R13.020.7491	2010-16	27/01/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT912B	R13.020.7869 (MRS.13)	2011-12	16/12/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT912B	R13.020.8195 (MRS.14.3)	2013-03	20/10/2006	Securitas Technology NV	Not Supported
MOTOROLA	MTP850	PT912B	R13.020.8462 (MRS.14.9)	2013-22	25/06/2010	Securitas Technology NV	Not Supported
MOTOROLA	MTP850EX	PT911B5Ex	R15.020.7186 (MRS.11.x)	2010-09	27/01/2013	Securitas Technology NV	Not Supported
MOTOROLA	MTP850EX	PT911B5Ex	R15.020.8195 (MRS.14.3)	2013-02	19/10/2010	Securitas Technology NV	Not Supported
MOTOROLA	MTP850S	PT912B5	R13.020.8195 (MRS.14.3)	2012-06	27/11/2012	Securitas Technology NV	Not Supported
MOTOROLA	MTP850S	PT912B5	R13.020.8462 (MRS.14.9)	2013-23	16/12/2013	Securitas Technology NV	Not Supported
MOTOROLA	MPX600	PTW952HEB	R55.020.9541 (MR2020.1)	2021-01	08/01/2021	Securitas Technology NV	Not Supported
MOTOROLA	MPX600	PTW952HEB	R55.020.9645 (MR2021.2)	2021-17	17/08/2021	Securitas Technology NV	Supported
MOTOROLA	MPX600	PTW952HEB	R55.020.9689 (MR2022.3)	2022-12	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	ST7000	PTM412DE	R37.020.9174 (MR 16.5)	2017-21	19/12/2017	Securitas Technology NV	Not Supported
MOTOROLA	ST7000	PTM412DE	R37.020.9289 (MR17.3)	2019-10	26/02/2019	Securitas Technology NV	Not Supported
MOTOROLA	ST7000	PTM412DE	R37.020.9363 (MR18.5)	2019-17	26/07/2019	Securitas Technology NV	Not Supported
MOTOROLA	ST7000	PTM412DE	R37.020.9426 (MR19)	2020-13	04/08/2020	Securitas Technology NV	Supported
MOTOROLA	ST7000	PTM412DE	R37.020.9689 (MR2021.3)	2022-08	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	ST7500	PTM412DER	R37.020.9289 (MR17.3)	2019-11	26/02/2019	Securitas Technology NV	Not Supported
MOTOROLA	ST7500	PTM412DER	R37.020.9363 (MR18.5)	2019-18	26/07/2019	Securitas Technology NV	Not Supported
MOTOROLA	ST7500	PTM412DER	R37.020.9426 (MR19)	2020-14	04/08/2020	Securitas Technology NV	Supported
MOTOROLA	ST7500	PTM412DER	R37.020.9689 (MR2021.3)	2022-09	06/05/2022	Securitas Technology NV	Supported
MOTOROLA	TOM100	OT911	R11.020.1058	2010-01	31/01/2010	Securitas Technology NV	Not Supported
NOKIA	THR420	HRU420-02	HY21.2011	2003-03	21/03/2003	TranzCom	Not Supported
NOKIA	THR420	HRU420-02	HY21.05-1	2003-17	09/02/2004	TranzCom	Not Supported
NOKIA	THR850	THR-3	V5.08-0	2004-04	21/02/2006	TranzCom	Not Supported

LIST OF ALL VALIDATED RADIOS TILL JUNE 2022

Astrid Support = Not supported - equipment was validated and can still be in use on the network but **Astrid will give no support** in case of eventual working issues

Astrid Support = Supported - equipment was validated and can be used on the network. **Astrid will give support** in case of eventual working issues

Manufacturer	Model	RadioType	Software Version	Certificate Nr	Validation date	Supplier	Astrid Support
NOKIA	THR850	THR-3	V5.08-1	2006-15	04/12/2003	TranzCom	Not Supported
NOKIA	THR880	THR-4	V6.15-3	2003-18	08/07/2004	TranzCom	Not Supported
NOKIA	THR880	THR-4	V7.34-0	2004-19	24/06/2005	TranzCom	Not Supported
NOKIA	THR880	THR-4	V7.60-0	2005-21	13/05/2007	TranzCom	Not Supported
NOKIA	THR880	THR-4	V7.68-2	2007-12	24/06/2008	TranzCom	Not Supported
NOKIA	THR880i	RC-2	V2.19-2	2004-23	16/06/2005	TranzCom	Not Supported
NOKIA	THR880i	RC-2	V3.19-2	2005-20	12/10/2005	TranzCom	Not Supported
NOKIA	THR880i	RC-2	V3.37-1	2005-27	13/02/2006	TranzCom	Not Supported
NOKIA	TMR420	MRU400-05	HQ21.2011	2003-02	04/12/2003	TranzCom	Not Supported
NOKIA	TMR420	MRU400-05	HQ21.03-1	2003-16	21/03/2003	TranzCom	Not Supported
PICIORGROS	TMO-100	TMO-100	V2.81	2013-18	07/10/2013		Not Supported
SEPURA	SC20	TP01STW	V1727 012 08522 (SC1.2-001)	2016-08	12/06/2016	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1738 004 08522 (SC1.4-001)	2017-02	17/01/2017	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1741 005 08522 (SC1.5-001)	2017-03	09/04/2017	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1746 012 08522 (SC1.7-001)	2017-11	23/10/2017	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1746 029 08522 (SC1.7-004)	2018-11	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1760 006 08522 (SC1.11-003)	2019-06	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1777 007 08522 (SC2.0-021)	2020-02	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1788 003 08522 (SC3.0-001)	2020-15	19/11/2020	Abiom Communications Systems	Not Supported
SEPURA	SC20	TP01STW	V1791 016 08522 (SC 3.1.003)	2021-12	20/07/2021	Abiom Communications Systems	Supported
SEPURA	SC20	TP01STW	V1804 001 08522 (SC 3.1.005)	2022-01	14/03/2022	Abiom Communications Systems	Supported
SEPURA	SC21	TP01STW	V1746 012 08522 (SC1.7-001)	2017-10	23/10/2017	Abiom Communications Systems	Not Supported
SEPURA	SC21	TP01STW	V1746 029 08522 (SC1.7-004)	2018-10	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	SC21	TP01STW	V1760 006 08522 (SC1.11-003)	2019-05	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	SC21	TP01STW	V1777 007 08522 (SC2.0-021)	2020-03	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	SC21	TP01STW	V1788 003 08522 (SC3.0-001)	2020-16	19/11/2020	Abiom Communications Systems	Not Supported
SEPURA	SC21	TP01STW	V1791 016 08522 (SC 3.1.003)	2021-13	20/07/2021	Abiom Communications Systems	Supported
SEPURA	SC21	TP01STW	V1804 001 08522 (SC 3.1.005)	2022-02	14/03/2022	Abiom Communications Systems	Supported
SEPURA	SRB9000	RSLTW2	V1711 034 02937 (V10.14-022)	2015-05	25/05/2015	Abiom Communications Systems	Not Supported
SEPURA	SRB9000	RSLTW2	V1711 038 02937 (V10.14-025)	2015-16	02/12/2015	Abiom Communications Systems	Not Supported
SEPURA	SRC3000	PSETN201T400G	V1582 000 01002	2006-36	12/09/2006	Abiom Communications Systems	Not Supported
SEPURA	SRC3300	PSETN201T400G	V1502 005 01002	2006-25	12/12/2006	Abiom Communications Systems	Not Supported
SEPURA	SRC3300	PSFTW201T400G00	V1631 006 02786 (V7.2-005)	2007-19	10/01/2008	Abiom Communications Systems	Not Supported
SEPURA	SRC3300	PSFTW201T400G00	V1631 006 01002 (V7.2-003)	2008-01	11/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRC3300	PSFTW201T400G00	V1639 005 02935	2008-05	04/03/2008	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSDTL201T2HCG00	V1481 039 01170	2006-19 / 2006-20	17/05/2006	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSDTL201T2HCG00	V1582 000 01170	2007-01	08/01/2007	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSDTL201T2HCG00	V1611 003 01170 (V7)	2007-06	07/03/2007	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSKTW201T2CCG00	V1631 006 01170 (V7.2)	2007-14	18/07/2007	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSKTW201T2CCG00	V1631 006 02788 (V7.2-005)	2007-18	11/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSKTW201T2CCG00	V1639 005 02936 (V8.0-001)	2008-06	11/03/2008	Abiom Communications Systems	Not Supported
SEPURA	SRG3500	MSCTL201T2HCG00	V1667 023 02936 (V10.0-008)	2011-02	15/05/2011	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1667 009 03577 (V10.0-005)	2010-11	25/07/2010	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1667 023 03577 (V10.0-008)	2011-02	28/03/2011	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1703 005 03577 (V10.11-001)	2013-16	06/06/2013	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1703 010 03577 (V10.11-005)	2014-06	03/02/2014	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1711 035 03577 (V10.14-022)	2015-04	17/05/2015	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1711 038 03577 (V10.14-025)	2016-02	20/01/2016	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1746 012 03577 (V10.21-002)	2017-15	06/11/2017	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1746 028 03577 (V10.21-004)	2018-15	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	SRG3900	MSUTW201T2COG00	V1760 006 03577 (V10.22-003)	2019-09	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	SRG3900 Series	MSUTW201T2COG00	V1781 003 03577 (V10.24-022)	2020-06	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	SRG3900 Series	MSUTW201T2COG00	V1788 003 03577 (V10.25-001)	2021-04	28/01/2021	Abiom Communications Systems	Not Supported
SEPURA	SRG3900 Series	MSUTW201T2COG00	V1791 016 03577 (V10.26-003)	2021-16	04/08/2021	Abiom Communications Systems	Supported
SEPURA	SRG3900 Series	MSUTW201T2COG00	V1804 001 03577 (V10.26-005)	2022-05	15/03/2022	Abiom Communications Systems	Supported
SEPURA	SRH3000	PS9TL201T40BG00	V1473 013 01002	2005-26	18/07/2006	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PS9TL201T40BG00	V1510 007 01002	2006-17	02/05/2006	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PS9TN201T400G00	V1502 005 01002	2006-22 / 2006-23	16/11/2006	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PS9TN201T400G00	V1582 000 01002	2006-32	18/05/2007	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PSHTW201T400G00	V1610 004 01002 (V7)	2007-04 / 2007-13	18/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PSHTW201T400G00	V1631 006 02786 (V7.2-005)	2007-16	11/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PSHTW201T400G00	V1631 006 01002 (V7.2-003)	2007-20	26/02/2008	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PSHTW201T400G00	V1639 005 02935 (V8.0-001)	2008-03	25/07/2010	Abiom Communications Systems	Not Supported
SEPURA	SRH3000	PSPTW201T400G00	V1667 023 03150 (V10.0-008)	2011-03	24/06/2013	Abiom Communications Systems	Not Supported
SEPURA	SRH3900	PSPTW201T400G00	V1667 009 03150 (V10.0-005)	2010-12	17/05/2015	Abiom Communications Systems	Not Supported
SEPURA	SRH3900	PSPTW201T400G15	V1703 005 03150 (V10.11-001)	2013-17	02/12/2015	Abiom Communications Systems	Not Supported
SEPURA	SRH3900	PSPTW201T400G15	V1711 034 03150 (V10.14-022)	2015-03	06/11/2017	Abiom Communications Systems	Not Supported
SEPURA	SRH3900	PSPTW201T400G15	V1711 038 03150 (V10.14-025)	2015-14	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	SRH3900	PSPTW201T400G15	V1746 012 03150 (V10.21-002)	2017-16	15/05/2011	Abiom Communications Systems	Supported
SEPURA	SRH3900	PSPTW201T400G15	V1746 028 03150 (V10.21-004)	2018-16	29/03/2011	Abiom Communications Systems	Supported
SEPURA	SRH3X00	PSPTW201T400G00	V1667 023 03150 (V10.0-008)	2011-03	15/11/2005	Abiom Communications Systems	Not Supported
SEPURA	SRM1000	MS1TT201T20C00	V1411 005 00010	2005-30	18/11/2005	Abiom Communications Systems	Not Supported
SEPURA	SRM2000	MS6TS201T22CG00	V1472 003 00340	2005-32	13/03/2006	Abiom Communications Systems	Not Supported
SEPURA	SRM2000	MS6TS201T22CG00	V1510 010 00340	2006-16	17/04/2007	Abiom Communications Systems	Not Supported
SEPURA	SRM2000	MS6TS201T22CG00	V1611 003 00340 (V7)	2007-11	26/09/2006	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTL201T2HCG00	V1510 007 01170	2006-18	03/05/2006	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTN201T2CCG	V1502 018 01170 (E2EE)	2006-26	26/09/2006	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTN201T2CCG	V1560 018 01170	2006-26	16/11/2006	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTN201T2CCG00	V1582 000 01170 (V6.5-G01)	2006-33	07/03/2007	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTN201T2CCG00	V1611 003 01170 (V7)	2007-05	18/07/2007	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSJTW201T2CCG00	V1631 006 01170 (V7.2)	2007-15	11/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSJTW201T2CCG00	V1631 006 02788 (V7.2-005)	2007-17	26/02/2008	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSJTW201T2CCG00	V1639 005 02936 (V8.0-001)	2008-04	15/05/2011	Abiom Communications Systems	Not Supported
SEPURA	SRM3500	MSCTL201T2HCG00	V1667 023 02936 (V10.0-008)	2011-02	27/10/2005	Abiom Communications Systems	Not Supported
SEPURA	SRP1000	PS3TT201T30000B	V1411 005 00012	2005-29	04/10/2005	Abiom Communications Systems	Not Supported
SEPURA	SRP2000	PS5TS201T420G1J	V1473 013 00014 (V5.0-006)	2005-25	07/05/2007	Abiom Communications Systems	Not Supported

LIST OF ALL VALIDATED RADIOS TILL JUNE 2022

Astrid Support = Not supported - equipment was validated and can still be in use on the network but **Astrid will give no support** in case of eventual working issues
 Astrid Support = Supported - equipment was validated and can be used on the network. **Astrid will give support** in case of eventual working issues

Manufacturer	Model	RadioType	Software Version	Certificate Nr	Validation date	Supplier	Astrid Support
SEPURA	SRP2000	PS5TS201T420G1J	V1610 004 00014 (V7)	2007-10	18/10/2007	Abiom Communications Systems	Not Supported
SEPURA	SRP2000	PS5TS201T420G1J	V1631 006 00014 (V7.2-003)	2007-21	04/10/2005	Abiom Communications Systems	Not Supported
SEPURA	STP8038	PSNTW201T300P0001	V1643 004 02937 (V8.6-001)	2008-14	13/10/2008	Abiom Communications Systems	Not Supported
SEPURA	STP8038	PSNTW201T300P0001	V1643 007 02937 (V8.6-002)	2008-15	25/11/2008	Abiom Communications Systems	Not Supported
SEPURA	STP8238	PSXTW201T300M0001	V1667 018 02937 (V10.0-007)	2010-15	20/09/2010	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1746 012 02937 (V10.21-002)	2017-13	29/04/2013	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1746 028 02937 (V10.21-004)	2018-13	03/02/2014	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1760 006 02937 (V10.22-003)	2019-08	17/05/2015	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1781 003 02937 (V10.24-022)	2020-05	02/12/2015	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1788 003 02937 (V10.25-001)	2020-18	23/10/2017	Abiom Communications Systems	Not Supported
SEPURA	STP8X	PSXTW201T400R0001	V1791 016 02937 (V10.26-003)	2021-14	20/07/2021	Abiom Communications Systems	Supported
SEPURA	STP8X	PSXTW201T400R0001	V1804 001 02937 (V10.26-005)	2022-04	15/03/2022	Abiom Communications Systems	Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1746 012 02937 (V10.21-002)	2017-12	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1746 028 02937 (V10.21-004)	2018-12	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1760 006 02937 (V10.22-003)	2019-07	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1781 003 02937 (V10.24-022)	2020-05	19/11/2020	Abiom Communications Systems	Not Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1788 003 02937 (V10.25-001)	2020-18	23/10/2017	Abiom Communications Systems	Not Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1791 016 02937 (V10.26-003)	2021-14	20/07/2021	Abiom Communications Systems	Supported
SEPURA	STP8x00	PSNTW201T300P2401	V1804 001 02937 (V10.26-005)	2022-04	15/03/2022	Abiom Communications Systems	Supported
SEPURA	STP8X138	PSXTW201T400R0001	V1703 005 02937 (V10.11-001)	2013-09	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	STP8X138	PSXTW201T400R0001	V1703 010 02937 (V10.11-005)	2014-05	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	STP8X138	PSXTW201T400R0001	V1711 034 02937 (V10.14-022)	2015-02	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	STP8X138	PSXTW201T400R0001	V1711 038 02937 (V10.14-025)	2015-13	19/11/2020	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300R0001	V1667 009 02937 (V10.0-005)	2010-10	28/07/2010	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300R0001	V1667 023 02937 (V10.0-008)	2011-01	29/03/2011	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300R0001	V1703 005 02937 (V10.11-001)	2013-08	29/04/2013	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300R0001	V1703 010 02937 (V10.11-005)	2014-03	03/02/2014	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300P2401	V1711 034 02937 (V10.14-022)	2015-06	08/06/2015	Abiom Communications Systems	Not Supported
SEPURA	STP8x38	PSNTW201T300P2401	V1711 038 02937 (V10.14-025)	2015-15	02/12/2015	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1746 012 02937 (V10.21-002)	2017-14	23/10/2017	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1746 028 02937 (V10.21-004)	2018-14	04/04/2018	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1760 006 02937 (V10.22-003)	2019-07	05/02/2019	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1781 003 02937 (V10.24-022)	2020-04	14/02/2020	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1788 003 02937 (V10.25-001)	2020-17	19/11/2020	Abiom Communications Systems	Not Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1791 016 02937 (V10.26-003)	2021-15	20/07/2021	Abiom Communications Systems	Supported
SEPURA	STP9x00	PSYTW201T300N0001	V1804 001 02937 (V10.26-005)	2022-03	14/03/2022	Abiom Communications Systems	Supported
SEPURA	STP9x38	PSYTW201T300N0001	V1703 005 02937 (V10.11-001)	2013-10	29/04/2013	Abiom Communications Systems	Not Supported
SEPURA	STP9x38	PSYTW201T300N0001	V1703 010 02937 (V10.11-005)	2014-04	03/02/2014	Abiom Communications Systems	Not Supported
SEPURA	STP9x38	PSYTW201T300N0001	V1711 034 02937 (V10.14-022)	2015-01	17/05/2015	Abiom Communications Systems	Not Supported
SEPURA	STP9x38	PSYTW201T300N0001	V1711 038 02937 (V10.14-025)	2015-12	02/12/2015	Abiom Communications Systems	Not Supported
SEPURA	SCG22	TG01TSU	V1804 001 10317 (V10.26-005)	2022-13	06/05/2022	Abiom Communications Systems	Supported
TELTRONIC	HTT500	N/A	V03.00.08	2008-11	30/06/2008	Verdi BVBA	Not Supported
TELTRONIC	MDT400	N/A	V14.02.00	2007-07	08/03/2007	Verdi BVBA	Not Supported